MS4 Annual Report Form

This report is being submitted for the reporting period ending March 9, 2013

If submitting this form as part of a joint report on behalf of a coalition leave SPDES ID blank.

Name of MS4/Coalition: South Glens Falls

SPDES ID: NYR20A091

3.b. What types of illicit discharges have been found during this reporting period?

- ○ Broken Lines From Sanitary Sewer
- ○ Cross Connections
- ○ Failing Septic Systems
- ○ Floor Drains Connected To Storm Sewers
- ○ Illegal Dumping
- ○ Other:
- ○ Industrial Connections
- ○ Inflow/Infiltration
- ○ Pump Station Failure
- ○ Sanitary Sewer Overflows
- ○ Straight Pipe Sewer Discharges
- ● None

4. How many illicit discharges/potential illegal connections have been detected during this reporting period? 0

5. How many illicit discharges have been confirmed during this reporting period? 0

6. How many illicit discharges/illegal connections have been eliminated during this reporting period? 0

7. Has the storm sewershed mapping been completed in this reporting period? ● Yes ○ No

If No, approximately what percent was completed in this reporting period? %

8. Is the above information available in GIS? ○ Yes ● No

Is this information available on the web? ○ Yes ● No

If Yes, provide URL(s):

Please provide specific address of page where map(s) can be accessed - not home page.

URL

URL